



STONE EDGING MACHINE

OPERATION'S MANUAL



The total or partial reproduction of this manual
is prohibited by any means, whether printed or electronic;
without the prior, express and written authorization of the author.

STONE EDGING MACHINE

OPERATION'S MANUAL

INDEX

| GENERAL SAFETY INSTRUCTIONS..... 4
| CAUTION 5
| OPERATING INSTRUCTIONS..... 6

GENERAL SAFETY INSTRUCTIONS

WARNING: To reduce the risk of injury, read all instructions properly.

Failure to follow the instructions listed below can cause electric shock, fire, serious injuries, mutilation and/or damage to the equipment.

A. SAFETY IN THE WORK AREA.

- * Keep the work area clean and lit. Crowded or dark areas lead to accidents.
- * Keep children, customers, and non-company personnel away from the electrical and mechanical operation area of the equipment.
- * It is recommended to have a minimum space of one meter or three feet around the machine for safety measure and to optimize work.

B. ELECTRICAL SAFETY.

- * Machinery connections must be adapted to the power outlets.
- * Do not use adapters for the switches: since you run the risk of receiving an electric shock.
- * Do not expose the switches and/or electrical connections to rain or humidity. If water enters these elements, there is a risk that they will break down or suffer an electric shock.
- * Use cable in a single piece, if there are joints in the connections these can produce a short circuit.
- * Do not expose cables or electrical connections to heat, oil, sharp edges, or moving parts, as damaged cables can cause electric shock or short circuit.

C. PERSONAL SAFETY.

- * Do not operate the equipment if you are tired, under the influence of alcohol or drugs.
- * Wear appropriate clothing, do not wear loose clothing, or necklaces, earrings, watches, if you have long hair wear a tie to keep it up.
- * Do not climb on the structure of the machine for any reason, falls or injuries may occur.
- * Avoid using headphones, cell phones or any other equipment that works as a distraction to the operator.
- * Make correct use of personal protective equipment if any maintenance is to be carried out on the machine.
- * If any change is made to the model or component of the equipment, be it electrical or mechanical related, it must be de-energized and stop the machine completely to avoid accidents.
- * Keep limbs away from all moving parts.

CAUTION

The following symbols indicate the safety measures that must be taken before and after starting up the equipment.



ELECTRICAL RISK In which you can suffer electric shocks, if you do not comply with the electrical safety provisions.

STONE EDGING MACHINE

MANUAL DE OPERACIÓN

INSTALACIÓN ELÉCTRICA

Verificar que la conexión eléctrica sea de 220v. Sin cortos circuitos ni cables sueltos o sin aislamiento.



INSTALACIÓN ELÉCTRICA	
A	220v (Trifásico o bifásico, según sea el caso).
B	Cable calibre 8 (entubado).

STONE EDGING MACHINE

MANUAL DE OPERACIÓN



1

Coloque el maneral en la flecha lateral y apriete el opresor.



2

Coloque la abrazadera de aluminio en la pulidora y apriete en los 3 lados con los tornillos incluidos.




3

Coloque el disco de corte en la pulidora y apriete.




4

Ensamble la abrazadera y apriete con la perilla.



5

Ajuste altura de la pulidora, libere la perilla lateral y comience a girar la perilla superior.




6

Coloque la piedra en el plato giratorio utilizando las guías.

7


STONE EDGING MACHINE

MANUAL DE OPERACIÓN



7

Conecte la pulidora a toma de corriente a 110 volts.




8

Gire la perilla hasta obtener la profundidad de rayado deseada.



9

Encienda la pulidora para empezar a trabajar la piedra.



10

Utilice el maneral para girar el plato cuando sea necesario.



PLANTA

AV. INDUSTRIAS #3655, ZONA INDUSTRIAL
CP 78395 SAN LUIS POTOSÍ, SLP. MÉXICO



444 127 11 80



444 129 29 79

info@manufacturaslenin.mx

TORTILLADORASLENIN.COM